



# I-95 AT NEABSCO CREEK – THE IMPORTANCE OF A GEOTECHNICAL INVESTIGATION

Southeastern Transportation Geotechincal Engineering
Conference

September 18, 2025

David Shiells, P.E. and Carlin Hall, P.G.

### **Project Location**






#### **Background**

- I-95 SB and NB Bridges completed in 1963
- Deck problems; multiple repairs
- I-95 HOV Bridge completed in 1996
- Phased replacement with open-bottom arch
- Easier for MOT and future maintenance
- Biggest arch structure in Virginia!




#### **Proposed Precast Arch**






#### **Proposed Precast Arch**






# **Proposed Precast Arch**





# Geology





#### **Geotechnical Challenges**

- Steep slopes down to Neabsco Creek
- Bridges approx. 70' to 80' above creek
- Graphitic slate is highly variable and low strength
- Quartz veins hard on core bits
- Pyrite inclusions (chemical concerns)
- Difficult to access boring locations due to exposed rock
- Not allowed to use bridge deck for crane (poor condition)




#### **Background – Historical Problems**

- Slope failure during construction of I-95 HOV bridge
- Bridge was ready for opening to traffic
- Geotechnical investigation
- Steep/tall slope with graphitic soil fill over soft clay fill
- South abutment demolished and reconstructed
- Slope benched with geogrid/open graded stone
- Capped with low density cementitious fill (LDCF)
- First application of LDCF in Virginia



#### **Project Location**





# **Slope Failure During Construction**





# **Geotechnical Investigation**






# **Drilling Through Bridge Deck**








#### **Subsurface Profile**






#### **Subsurface Cross-Section**






#### **Slope Repair**






# **Bridge Deck Removal**





# **Exposed Rock on Slope Face**





# **Benching Slope on South Abutment**






# **Low Density Cementitious Fill (LDCF)**






#### **Back to the Present**






#### **Back to the Present**






# **Scoured Rock**





# **Scoured Rock**





#### **Dry Run at Manassas**


- Met with Virginia Crane and Willow Spring
- Spreader bar recommended
- Make sure rig is in good operating order (replaced battery)
- Weld lift hooks to trailer







#### **Equipment Modifications**





#### **Traffic Control Plan**

- Double Lane closure on I-95
- Rest Area Accel. Lane closure
- Limited hours (10 pm to 5 am)
- Approval from TOC (LCAMs) and Traffic Operations
- Staging area for crane and tractor trailers (Rest Area)



#### **Crane Set-Up**





### Crane Set-Up





# **Crane Set-Up**





#### **Pad Set-Up**






#### **Pad Set-Up**





#### **Site Safety**




#### **Site Safety**





#### **Crane Lift**






### **Crane Lift**








#### **Rock Variability**





#### **Rock Core Photos**





#### **Rock Core Photos**





#### **Corrosive Soils**

Test	Standard for Corrosive Environment	Result for B-5, Depth 1'-5' below Ground Surface
рН	<6.0	3.7
Resistivity	<3,000 ohm-cm	1,800 ohm-cm
Chlorides	>100 ppm	19 ppm
Sulfates	>200 ppm	288 ppm

Result – environment is corrosive; allow 0.1" sacrificial thickness for steel piles

Ref.: Structure & Bridge Manual, File No. 23.05



### Current Design Status – Back to Bridge Widening!





#### **Acknowledgements**

Owner – Virginia Dept. of Transportation VDOT Project Manager – Vicente Valeza, P.E. Design Engineer – Hardesty and Hanover Transurban – I-95 Express Concessionaire



# Questions?



